


Figure 1: Pointcloud received from client, including internal and external data.






Figure 2: Ground and First Floor Plans of fire damaged units, including attached outbuildings.



Figure 3: Front and rear elevations of retail units, showing extent of damage to roof and roof structure.